




DUCHY *of* CORNWALL
HARBOUR OFFICE ST MARY'S ISLES OF SCILLY

LOCAL NOTICE TO MARINERS
No. 03/25

ST MARY'S HARBOUR
SUNKEN MOORING – TEAN SOUND

Mariners are advised that in position “49.57.911N 006.18.394W” a green mooring buoy has been dragged under water and remains a hazard to passing vessels through Tean Sound.



LNtM in Force - 08/16 - Seasonal water intake at Pelistry Bay (St Mary's)

All LNtMs are available online at www.stmarys-harbour.co.uk

Dale Clark,
Harbour Master,
St Mary's Harbour,
Isles of Scilly